cotc

#30 Fms

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

HESSEL, Lasse

Patent Number 4,976,273

Serial Number: (Filed January 27, 1988) 07/148,992 :

Issue Date December 11, 1990

TUBULAR PROTECTIVE DEVICE FOR PROTECTION For

AGAINST TRANSFER OF INFECTIOUS MATTER

DURING SEXUAL INTERCOURSE

PATENT & TRADEMARK OFFICE REQUEST FOR CERTIFICATE OF CORRECTION RECEIVED

The Honorable Commissioner of Patents and Trademarks Washington, D.C. 20231

. Sir:

Please issue a Certificate of Correction identified patent correcting the errors listed on the enclosed PTO Form-1050.

The errors in the issued patent include mistakes incurred through the fault of the U.S. Patent and Trademark Office. mistakes include mistakes that are of a nature that the meaning intended is not obvious from the context, and thus should be subject to a Certificate of Correction. These mistakes which are the fault of the U.S. Patent and Trademark Office are listed below:

In the Related U.S. Application Data, line 1, "Jun. 15, 1987" should read --Jun. 5, 1987--;

In the Other Publications, line 4, "1934," should read --1934),--;

In the Other Publications, line 7, "condoms-using" should read --Condoms Using--;

Column 1, line 62 "device This" should read --device. - to correspond with page 3, line 7 of the application;

050 LP 06/17/92 4976273 050 LP 06/17/92 4976273

Column 3, line 41 "virus" should read --virus, -- to correspond with page 7, line 23 of the application;

Column 4, line 62 "elastric" should read --elastic-- to correspond with page 11, line 17 of the application; and

Column 6, line 27 "rounded At" should read --rounded. At-to correspond with page 15, line 24 of the application.

The errors in the issued patent also include mistakes of a clerical or typographical nature, or of minor nature, which are not the fault of the U.S. Patent and Trademark Office and occurred in good faith. Correction of these mistakes does not involve such changes in the patent as would constitute new matter or would require re-examination. The mistakes which are not the fault of the U.S. Patent and Trademark Office are listed below:

At page 25, line 5 of the application and in the Abstract, line 4 of the patent "end" should read --end having--;

At page 3, line 5 of the application and at column 1, line 60 of the patent "are" should read --is--;

At page 3, line 18 of the application and at column 2, line 5 of the patent "useful" should read --not useful--;

At page 5, line 5 of the application and at column 2, line 42 of the patent "thin-walled," should read --thin-walled--;

At page 6, line 2 of the application and at column 2, line 61 of the patent "condom like" should read --condom-like--;

At page 10, line 1 of the application and at column 4, line 22 of the patent "is" should read --are--;

At page 14, line 6 of the application and at column 5, line 55 of the patent "a insertion" should read --an insertion--;

At page 14, line 10 of the application and at column 5, line 59 of the patent "inserted" should read --insertion--;

At page 16, line 13 of the application and at column 6, line 41 of the patent "2" should read --2 of-- and "1" should read --1,--;

U.S.S.N.: 07/148,532

Page 3

At page 17, line 20 of the application and at column 7, line 6 of the patent "that" should read --than--;

At page 18, line 4 of the application and at column 7, line 15 of the patent "internal of" should read --internal or--; and

At page 18, line 6 of the application and at column 7, line 17 of the patent "attatched" should read --attached--.

Enclosed is a check in the amount of \$70.00 in payment of the fee for correction of applicants mistake. Also enclosed is a check in the amount of \$4.50 in payment of the fee for 15 additional copies of the certificate of correction. Please charge or credit Deposit Account Number 12-1210 if the amount of either check is incorrect.

June 1, 1992

Karen Lee Orzechowski

Reg. No. 31,621

Attorney for Applicant

LEVY, ZITO & GRANDINETTI Suite 411 1910 K Street, N.W. Washington, D.C. 20006-1104

(202) 429-4560